



Calibrating Your Promethean Board to Use the Touch Screen

1. Right click the Promethean icon on the **system tray**. It is located at the bottom right of your PC.



2. Click Calibration. Then, select 5 points.



3. You will see the following screen. Use one of your pens to touch the center of each of the crosses on the board to finish the calibration.

